



4321 North Knox Avenue, Chicago, Illinois 60641 USA
Phone: 773-777-7100 Fax: 773-777-0909
www.awt-gpi.com

MATERIAL SAFETY DATA SHEET

MANUFACTURER'S NAME

A.W.T. WORLD TRADE, INC.

ADDRESS

4321 North Knox Avenue
Chicago, Illinois 60641

PHONE: 773-777-7100 FAX: 773-777-0909

EMERGENCY TELEPHONE NO.

CHEM-TEL 800-255-3924

ISSUE DATE

April 28, 2006

SECTION I IDENTIFICATION OF PRODUCT

PRODUCT NAME: Water Soluble Block-Out

PRODUCT CODE: BL-15R/BL-15C BL-25HB

SECTION II HAZARDOUS INGREDIENTS

INGREDIENTS CAS # WEIGHT MAX.% EXPOSURE LIMITS

This section not applicable

SECTION III PHYSICAL DATA

APPEARANCE AND ODOR	Red or Clear
ODOR	Low, Pleasant, Sweet
BOILING POINT (°F)	Approx. 212°F
VAPOR PRESSURE (mm Mercury)	--
VAPOR DENSITY (Air=1)	Lighter than air
SOLUBILITY IN WATER	Water Miscible
SPECIFIC GRAVITY (Water=1)ca	1.1
PERCENT VOLATILE BY VOLUME (%)	75 - 80%
EVAPORATION RATE (-----=1)	Slower than Ether
WEIGHT/GAL.	9.00

=====
This information is furnished without warranty, representation, inducement or license of any kind, except that it is accurate to the best of A.W.T. World Trade, Inc., knowledge, or obtained from sources believed by A.W.T. World Trade, Inc., to be accurate, and A.W.T. World Trade, Inc., does not assure any legal responsibility for use or reliance upon same. Customers are encouraged to conduct their own tests. Before using any product, read its label.



4321 North Knox Avenue, Chicago, Illinois 60641 USA
Phone: 773-777-7100 Fax: 773-777-0909
www.awt-gpi.com

SECTION IV FIRE AND EXPLOSION HAZARD DATA

FLASH POINT **FLAM. LIMITS (% BY VOLUME)** **UEL** N/A **LEL** N/A
Greater than 200°F
EXTINGUISHING MEDIA
Water, carbon dioxide
SPECIAL FIRE FIGHTING PROCEDURES
Water should be used to keep fire exposed containers cool.
UNUSUAL FIRE AND EXPLOSION HAZARDS
There are no unusual fire or explosion hazards.

SECTION V HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE
TVL for vinyl acetate is 10 ppm
EFFECTS OF OVEREXPOSURE
No inhalation hazard is expected.
EMERGENCY AND FIRST AID PROCEDURES
Wash from the skin with soap & water. If splashed in the eye, flush with water for 15 minutes and seek medical attention. Small ingested amounts are not believed to have health effects.

SECTION VI REACTIVITY DATA

STABILITY () Unstable (X) Stable
CONDITIONS TO AVOID: None
INCOMPATIBILITY (Material to avoid): None known
HAZARDOUS POLYMERIZATION () May occur (X) Will not occur
HAZARDOUS DECOMPOSITION PRODUCTS
When adhesive burns, water, carbon dioxide, carbon monoxide, and smoke are produced.

=====
This information is furnished without warranty, representation, inducement or license of any kind, except that it is accurate to the best of A.W.T. World Trade, Inc., knowledge, or obtained from sources believed by A.W.T. World Trade, Inc., to be accurate, and A.W.T. World Trade, Inc., does not assure any legal responsibility for use or reliance upon same. Customers are encouraged to conduct their own tests. Before using any product, read its label.



4321 North Knox Avenue, Chicago, Illinois 60641 USA
Phone: 773-777-7100 Fax: 773-777-0909
www.awt-gpi.com

SECTION VII SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IF MATERIAL IS RELEASED OR SPILLED

Absorb with inert material (sand, vermiculite, etc.), sweep or scoop up and put in disposal container. Flush area immediately with plenty of water. Prevent washing from entering waterways.

WASTE DISPOSAL METHOD

Dispose of in accordance with Local, State, & Federal regulations.

SECTION VIII SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (specify type)

NIOSH approved organic vapor respirators are only required when ventilation is inadequate.

VENTILATION

General ventilation is recommended during normal use. Local ventilation may be required during certain operations to prevent inhalation of vapors.

PROTECTIVE GLOVES

Chemical-resistant nitrile, neoprene or rubber gloves required.

EYE PROTECTION

Wear face shield or chemical goggles.

OTHER PROTECTIVE EQUIPMENT

Wear protective clothing to prevent skin contact. Eye wash station and safety shower should be available.

SECTION IX SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Practice reasonable care and cleanliness. STORE ABOVE 40°F. DO NOT FREEZE

OTHER PRECAUTIONS

None

****END MSDS****

=====
This information is furnished without warranty, representation, inducement or license of any kind, except that it is accurate to the best of A.W.T. World Trade, Inc., knowledge, or obtained from sources believed by A.W.T. World Trade, Inc., to be accurate, and A.W.T. World Trade, Inc., does not assume any legal responsibility for use or reliance upon same. Customers are encouraged to conduct their own tests. Before using any product, read its label.